

~~CONFIDENTIAL~~

8 19593

CIA IMAGERY ANALYSIS DIVISION

NAME Lang Bun R. R Bridge Bridge No. 1 on NF 48-6	COUNTRY North Vietnam	COORDINATES 22 09N/104 23E VK 368493.
REFERENCES 25X1D PHOTO [REDACTED] MAP AMS 1509 NF 48-6		BRIEF NO: PTB - 65001


LOCATION: 0.5 nm NE of Lang Bun on the Hanoi - Lao Cai Rail Line

DESCRIPTION:

LENGTH	150'	MATERIAL	Steel and Concrete
WIDTH	Single Track	NO. OF SPANS	2
TYPE	Half-through Truss	LENGTH OF EACH SPAN	75'

STATUS: Moderately damaged, super structure twisted and in poor alignment, rail line interdicted on both approaches

COMPENSATIVE ACTION: None



Declass Review by NIMA/DOD

~~CONFIDENTIAL~~

GROUP 1
Excluded from automatic
downgrading and declassification